

**Agenda item: 5**

<b>Committee</b>	Assets & Services Committee
<b>Month</b>	October 2022
<b>Report Title</b>	Anglo American Playing Fields paly Equipment Refurbishment
<b>Report Author</b>	Georgia Arnold
<b>Attachments</b>	CAD Design - New equipment



**Summary**

This report provides an update on the Anglo-American Play Area Playing Fields (AAPF), play equipment refurbishment project.

The working group has appointed a contractor and a design has been agreed (CAD Design attached for information). The works are scheduled for completion in March 2023.

A summary of the differences in equipment is below:

<b>Current equipment</b>	<b>NEW Equipment</b>
<ul style="list-style-type: none"> <li>• Swings (junior and toddler)</li> <li>• Balance beams, trail, balance log frame, climbing blocks</li> <li>• Zip Wire</li> <li>• Large netted/rope climbing frame</li> <li>• Multi play junior unit</li> <li>• X2 springers</li> <li>• Multi play toddler unit</li> <li>• Rota rocka roundabout</li> </ul>	<ul style="list-style-type: none"> <li>• X3 flatbed swings</li> <li>• X1 bravo seat (netted) swing</li> <li>• X1 tango seat swing (parent and child)</li> <li>• X1 cradle seat swing (toddler seat)</li> <li>• X1 mirage seat swing (disabled user friendly)</li> <li>• Bespoke trail walk, stepping stones, balance beam and rope walk</li> <li>• Zipwire</li> <li>• Large netted/rope climbing frame</li> <li>• Refurbished multi play junior unit</li> <li>• X2 Springers</li> <li>• Refurbished multi play toddler unit</li> <li>• Refurbished rota rocka roundabout</li> </ul> <p>New equipment types not previously at AAPF, these items were requested in the public consultation:</p> <ul style="list-style-type: none"> <li>• Slide</li> <li>• See Saw</li> <li>• Inclusive Roundabout</li> </ul>

This new design came together with input from:

- The public consultation
- Site visits with the contractor
- The working group, who have frequently discussed the designs with the contractor regarding the types of equipment and layout

### **Costs**

Removal old equipment costs = £10,950

Installation costs = £119,721.53

Total = £130,671.53

These costs have been budgeted for in the Anglo-American and special projects ear-marked reserves.